

BELZONA REPAIR TO MARINE ENGINE BLOCK


ID: 86

Industry: *Marine*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona® 1111 (Super Metal) ,*

Customer Location: *Marine repair shop*
Application Date: *1992*

Problem

Crankshaft Bearing shells spun in housing causing wear in the housing necessitating rebuilding before new shell bearings installed.



Photograph Descriptions

- * Application underway to the engine crankcase ,
- * Belzona® 1111 applied to housing ,
- * Line boring of housings underway ,

Application Situation

12 Cylinder Diesel engine from ship

Application Method

Application carried out in accordance with Belzona Know-How leaflet ENC-3.

Belzona Facts

Replacement crankcase would have cost in excess of \$100,000 and conventional welding repairs could not be guaranteed not to cause distortion. Belzona repairs cost \$1500 and were completed in 3 days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve