Fractured GRP pipe repaired with Belzona Super Wrap 2

ID: 9033

Industry:PowerCustomer Location: IrelandApplication:VPF-Valves, Pipes and FittingsApplication Date: March 2023

Substrate: GFRP

Products: Belzona 1212, Belzona 1983 (SuperWrap II)

Problem

A GRP pipe had shattered causing a partial shutdown of a power plant







Fractured 8" GRP pipe

Steel plate bonded over the hole with Belzona 1212

Damaged area reinforced using Belzona Super Wrap 2

Application Situation

Beltech received an emergency call from the plant which was in partial shutdown due to the pipe failure. The job was completed that day over a 6.hour period.

Application Method

The GRP was cleaned by grit blasting and a steel plate was bonded over the hole to act as a support for the reinforcing wrap

Belzona Facts

Carrying out the repair allowed the plant to resume production. Replacing the pipe was not possible within a reasonable time period