# Belzona quickly saves the ripped conveyor belt

ID: 9044

Industry: Mining & Quarrying Customer Location: Northern Croatia Application: SHM-Solids Handling Machinery Application Date: November 2022

Substrate: Rubber

**Products:** Belzona 2311 (SR Elastomer), Belzona 2911 (Elastomer QD Conditioner)

#### Problem

An incident in production caused damage to a conveyor belt. The belt was ripped through the middle in length of more than 1 m. The production had to stop.



Ripped conveyor belt



First layer of the belt peeled off Belt fasteners installed in order to install belt fasteners properly





Belt fasteners protected with Belzona 2311

## **Application Situation**

Customer contacted us for the emergency repair of the conveyor belt. We offered to do the repair the same day in the afternoon, so production could start again next morning.

## **Application Method**

First we peeled off (delaminated) the first layer of the belt in order to install belt fasteners in the way then aren't above the belt level. Then we installed belt fasteners, abraded them with the grinder and applied Belzona 2911 and Belzona 2311.

#### **Belzona Facts**

Customer was pessimistic about possibility of saving this belt and he was considering the replacement of the belt as the only alternative, which would be expensive and time consuming (minimal one additional production day would be lost). We did the repair for just a fraction of replacement price and with minimal production loss.

ISO 9001:2015 FS 695214 manufactured under an ISO ISO 14001:2015 9000 Registered Quality EMS 695213 Management System.