GALVANIC CORROSION IN WATER MAKER REPAIRED WITH BELZONA

ID: 908

Industry: Water / Wastewater Customer Location: FPSO UK, North Sea

Application: VPF-Valves, Pipes and Fittings Application Date: July 2002

Substrate: Carbon Steel

Products: * Belzona® 1111 (Super Metal),

* Belzona® 1321 (Ceramic S Metal),

Problem

Galvanic corrosion caused by the failure of the insulating gasket caused severe corrosion and under cut the existing glass flake coating. Base material was Carbon Steel plates were Titanium.









Photograph Descriptions

- * Water Maker,
- * One of the areas of galvanic corrosion,
- * Forming the repair ,
- * Repair completed, perfectly formed flange face,

Application Situation

The fresh water maker started to leak

Application Method

Application completed in accordance with Belzona System Leaflet VPF-13.

Belzona Facts

Weld repair would have damaged more of the existing coating and onsite machining would have had to be used to reinstate the sealing faces and the bore of the nozzles. Time was key factor as this was an emergency repair situation.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve