Belzona provides cavitation repair and protection for a large hydropower unit impeller

ID: 9115

Industry: Customer Location: a large hydropower plant in Hunan, Power

China

Application: FBC-Fans, Blowers and Compressors Application Date: March 2022

Substrate: Stainless-steel

Belzona1311, Belzona1341, Belzona2141, Belzona2941, **Products:**

Problem

Cavitation occurs at the top of Francis impeller in a hydropower station unit









the image of affected impeller Pitting corrosion before repair the surface after Belzona 1341 application completed application

Application Situation

The hydropower station locates in the main stream of Yuan River, the capacity of which is 2.4 million kW.

Application Method

The application was carried out in strict accordance with Belzona Know How leaflets FBC-1 and FBC-2. Belzona 1311 was used to repair the cavitation areas after grit blasting. Then, applied two coats of Belzona 1341 to improve fluid efficiency for the equipment. Finally, Belzona 2941 and Belzona 2141 were applied to protect the outer surface against cavitation and corrosion.

Belzona Facts

The impellers have been affected by cavitation for many years. In the past, they were repaired by welding every two years. After a period of time, cavitation occurred again. This caused repeated deformation of the impellers, resulting in power generation

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 FS 695214 manufactured under an ISO ISO 14001:2015 9000 Registered Quality EMS 695213 Management System.

www.belzona.com

the impellers have been checked and w clients were satisfied.	itnessed few cavitation of	Belzona 2141. Overall, th	e impellers were well prote	ected and