

BELZONA SEALS TRANSFORMER LID FLANGE

CUSTOMER

Gas Distributor, UK

APPLICATION DATE

2011

APPLICATION SITUATION

Lid gasket flange on this 66-11Kv transformer.

PROBLEM

Most of the gasket had failed around the 10m perimeter of the lid, with oil seeping down the sides and going to ground. Unfortunately it was not possible to drain the oil below the gasket level and so the application had to be pursued as a live leak with a 1m head pressure.

PRODUCTS

Belzona 1291 (ES-Metal)

Belzona 1221 (Super E-Metal)

Belzona 1161 (Super UW-Metal)

Belzona 5831 (ST-Barrier)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Application was carried out using Belzona Know-How System Leaflet VPF-11 as a guide. Area of flange and bolts were pressure cleaned and grit blasted. Live leaks stemmed with Belzona 1291 and Belzona 1221. Bolt heads top and bottom were encapsulated with Belzona 1161. Belzona 1161 and Belzona 9341 used to create a reinforced band around the flange. Finally over coated with Belzona 5831.

BELZONA FACTS

The customer was desperate for a fast solution to the problem and whilst there were a couple of very minor leaks still on completion, these were deemed to be well within acceptable limits. The customer was delighted with the results and is looking to repeat the application to other transformers on their site.

PICTURES

1. Original condition of flange with header tank at rear
2. Encapsulation of bolts with Belzona 1161
3. Completed repair close up
4. Finished work after 3 days



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA
Repair • Protect • Improve