

EASY LINTEL REPAIR WITH BELZONA

CUSTOMER

Housing Association, Cleveland, UK

APPLICATION DATE

2017

APPLICATION SITUATION

Residential Property

PROBLEM

The entire front face of the concrete "Boot" lintel had failed due to re-bar corrosion. The customer wanted a long-term solution without having the need to disturb the structure.

PRODUCTS

Belzona® 4141 (Magma-Build)

Belzona® 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete and Steel

APPLICATION METHOD

Application carried out in accordance with Belzona system leaflet WPA-4

BELZONA FACTS

The application was completed in just 2 hours. Conventional replacement would have been costly, time consuming and disruptive. The customer has used Belzona 4141 before and is very happy with the results.

PICTURES

1. Overview (after repair)
2. Damaged Lintel
3. Damaged Lintel
4. Completed repair

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA®
Repair • Protect • Improve