

CONDENSER RUBBER LINER REPAIRED WITH BELZONA

CUSTOMER

Power plant - Takoradi, Ghana

APPLICATION DATE

October 2018

APPLICATION SITUATION

Rubber liner of a Steam Condenser

PROBLEM

Existing condenser rubber liner peels off and corrosion starts to attack the metallic surface.

PRODUCTS

Belzona 2111 (D&A High-Build Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

Belzona 1111 (Super Metal)

SUBSTRATE

Rubber & Steel

APPLICATION METHOD

Application was done in accordance with Belzona Know-How System Leaflet GSS-1. After surface was prepared, we notice some amount of metal has been lost. Metallic surface was rebuilt with Belzona 1111. Belzona 2911 was applied on the next day, then Belzona 2111 was applied, using an applicator and brush.

BELZONA FACTS

The rubber liner was rebuilt with Belzona 2111 and is currently lasting and performing well when steam condenser is in service. The cost to repair is lower as compared to purchasing a new steam condenser for power generation. Belzona 2111 was selected because of the properties with respect to operating parameters.

PICTURES

1. Before the surface prep and application of Belzona 2111 and Belzona 1111
2. After Surface preparation using bristle blaster
3. After the application of Belzona 1111
4. After view when Belzona 2111 was applied



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

