

# Slurry Line Leak Repair – Cold-Applied Composite Solution at Cement Plant

ID: 10007

Industry: Mining & Quarrying

Customer Location: Bowmanville

Application: VPF-Valves, Pipes and Fittings

Application Date: September 2025

Substrate: Carbon steel

Products: Belzona 1161 (Super UW-Metal), Belzona 1984, Belzona SuperWrap II

## Problem

A rubber-lined slurry pipe inside a cement plant has developed an approx 1-inch diameter hole that has penetrated through the wall, resulting in an active leak of abrasive slurry.

Welding was not an option due to the presence of internal rubber lining.

Pipe was part of a critical production line, requiring a fast, strong, and reliable repair to avoid extended downtime.



A hole in a pipe before the application.



The surface has been prepared for the application



Rebuild with Belzona 1161 with 9341 mesh



Strengthening the repair with Super Wrap II with Belzona 1984

## Application Situation

An approximately 1-inch leak was detected on a rubber-lined slurry line in a cement plant. Welding was not possible due to the internal rubber lining.

To avoid costly shutdown and replacement, we offered a cold-applied solution using Belzona 1161 with 9341 mesh to seal and rebuild the defect, followed by SuperWrap II with 1984 resin for long-term reinforcement.

This approach enabled a fast, in-situ repair with significant cost and time savings — the line was back in service within a day.

## Application Method

Surface Preparation:

Leaking pipe surface roughened with the power tool to SSPC-SP10 standard, Surface cleaned and roughened to ensure high adhesion

Leak Sealing & Build-Up:

Belzona 1161 applied over leak zone, 9341 mesh embedded within 1161 to arrest leak and rebuild wall thickness. Cured and profiled as a foundation for the wrap system

Structural Wrapping:

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)



SuperWrap II system applied using 1984 resin with 9381 carbon fibre wrap and 9382 consolidation film.  
Applied in multiple layers to meet the thickness and strength required.

## Belzona Facts

Alternatives: Welded patch or pipe replacement (not feasible due to rubber lining)

Why Belzona?

- Cold-applied — no fire risk
- Compliant with pipe wrap standards
- Fast-curing, durable under abrasive and pressurized flow

Cost Savings: Avoided full pipe replacement, crane hire, and hot work permits

Time Savings: Repair completed on-site within a day

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

