

BELZONA REPARÉ LES FUITES D'HUILE SUR LES AILETTES D'UN TRANSFORMATEUR

ID: 2128

Industrie: **Énergie**

Application: **Vannes, tuyaux et raccords**

Substrat: **Acier**

Des produits: *** Belzona 1161 (Super UW-Metal)**,

Localisation du client: *Station de distribution électrique,
Royaume-Uni*

Date de la demande: **2008**

Problem

Fuites d'huile des ailettes.



Descriptions des photographies

* 1. Vue d'ensemble du transformateur. 2. Vue de près de la zone de fuite de l'huile. 3. Application achevée. Fuite étanchée avec Belzona 1161. ,

Cas d'application

Transformateur électrique refroidi à l'huile.

Procédé d'application

L'application a été effectuée en accord avec la procédure Belzona VPF-11a, utilisant un produit Belzona tolérant de l'état de surface

Faits sur Belzona

Le besoin coûteux de drainer l'huile afin d'effectuer la réparation a été éliminé. La réparation Belzona a été réalisée en moins de 2 heures et s'est avérée être un succès total.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com

