

BELZONA STOPS PREMATURE WEAR ON THIS RUBBER BELT

ID: 313

Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Quarry in Minnesota*
Application Date: *July 2000*

Substrate: *Rubber*
Products: ** Belzona® 2211 (MP Hi-Build),*

Problem

Gravel from the quarrying operation was wearing the clips out prematurely and creating unscheduled outages.



Photograph Descriptions

* View of conveyor belt from dredger Grinding down edges of new clips Conditioning repair area with Belzona® 2911 (QD Conditioner) Application of Belzona® 2211 (MP Hi-Build) ,

Application Situation

Conveyor belt clips from a dredger.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-4.

Belzona Facts

The repair was not put on too thick because of scraper arm concerns and flapping over the drive roller.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve