

BELZONA RENUEVA UN TAMBOR MOTRIZ DEFORMADO

ID: 4848

Industria: Minería y canteras
Solicitud: Maquinaria de Manejo de Sólidos
Sustrato: Goma
Productos: * Belzona 2211 (MP Hi Build Elastomer) ,

Ubicación del cliente: Mina de carbón en Macedonia
Fecha de aplicación: Agosto 2002

Problem

El tambor motriz tenía una cubierta de goma de 15 mm. La superficie del tambor se deformó mecánicamente durante su transporte con un montacargas.



Descripciones de fotografías

- * Vista del tambor dañado ,
- * Preparación de la zona deformada ,
- * Aplicación concluida ,

Situación de la aplicación

Tambor motriz de una correa transportadora revestido de goma

Método de aplicación

Aplicación se llevó a cabo de acuerdo al folleto de Sistema Belzona Know-How SHM-9.

Datos de Belzona

Esta era la única solución para la reconstrucción de la superficie del tambor deformado. El éxito de la reparación condujo a realizar otras aplicaciones similares en otros dos tambores.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Reparar • Proteger • Mejorar

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

