EASY LINTEL REPAIR WITH BELZONA

ID: 6435

Industry: Buildings & Structures Customer Location: Housing Association, Cleveland, UK

Application: WPA-Wall Problem Areas Application Date: 2017

Substrate: Concrete and Steel

Products: * Belzona® 4141 Belzona® 4911,

Problem

The entire front face of the concrete "Boot" lintel had failed due to re-bar corrosion. The customer wanted a long-term solution without having the need to disturb the structure.









Photograph Descriptions

- * 1. Overview (after repair),
- * 2 & 3. Damaged Lintel,
- * 4. Completed repair,

Application Situation

Residential Property

Application Method

Application carried out in accordance with Belzona system leaflet WPA-4

Belzona Facts

The application was completed in just 2 hours. Conventional replacement would have been costly, time consuming and disruptive. The customer has used Belzona 4141 before and is very happy with the results.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

