

# BELZONA RENEWS DEFORMED CONVEYOR DRIVE DRUM

ID: 663

Industry: *Mining & Quarrying*

Customer Location: *Coal mine in Macedonia*

Application: *SHM-Solids Handling Machinery*

Application Date: *August 2002*

Substrate: *Rubber*

Products: *\* Belzona® 2211 ( MP Hi Build Elastomer) ,*

## Problem

*The drive drum had a 15 mm rubber cover. The surface of the drum was mechanically deformed during transportation with fork lift truck.*



## Photograph Descriptions

\* View of the damaged drum Preparing the deformed area Finished application ,

## Application Situation

Rubber clad conveyor drive drum.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

## Belzona Facts

This was the only solution for rebuilding the deformed drum surface. The success of the repair lead to similar applications carried out on two more conveyor belt drums.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve