

Belzona SuperWrap seals weeping storage tank

ID: 1577

Industry: Power
 Application: VPF-Valves, Pipes and Fittings
 Substrate: Mild Steel
 Products: * Belzona® Superwrap ,

Customer Location: Energy Company
 Application Date: April, 2009

Problem

Vertical weld was found to be very porous and fuel oil was weeping from a 2 mm through wall defect. No corrosion or thin wall area was detected. Defect was located at 30 feet from the ground level.



Photograph Descriptions

- * Damaged area ,
- * Area prepared by abrasive blasting ,
- * Belzona® SuperWrap application ,
- * Belzona® SuperWrap repair inspected and painted over ,

Application Situation

220 foot diameter 56 foot high storage tank containing fuel oil at 140°F max. temperature.

Application Method

SuperWrap composite system was applied in compliance with ISO/TS 24817 and ASME PCC-2. Belzona® Superwrap composite repair system was applied at 10 mm thickness and over a 100 x 355mm area.

Belzona Facts

The repair was completed without resort to hotwork. Belzona® Superwrap System was inspected in 2010 and found to be in perfect

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA®
 Repair • Protect • Improve

condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

