

# BELZONA STOPS PREMATURE WEAR ON THIS RUBBER BELT

ID: 313

Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Quarry in Minnesota*  
Application Date: *July 2000*

Substrate: *Rubber*  
Products: *\* Belzona® 2211 (MP Hi-Build),*

## Problem

*Gravel from the quarrying operation was wearing the clips out prematurely and creating unscheduled outages.*



## Photograph Descriptions

\* View of conveyor belt from dredger Grinding down edges of new clips Conditioning repair area with Belzona® 2911 (QD Conditioner) Application of Belzona® 2211 (MP Hi-Build) ,

## Application Situation

Conveyor belt clips from a dredger.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-4.

## Belzona Facts

The repair was not put on too thick because of scraper arm concerns and flapping over the drive roller.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve