BELZONA REPAIRS TO RUBBER LINED CONDENSER

ID: 411

Industry: Power Customer Location: Power station - Ireland

Application: HEX-Heat Exchangers Application Date: 2003

Substrate: Rubber & Steel

Products: * Belzona® 2211 (MP Hi-Build Elastomer),

Problem

Spark testing of rubber lining highlighted several defects requiring repair.







Photograph Descriptions

- * Damaged areas of lining identifi ed and marked ready for repair. ,
- * The repair area masked off to ensure application is kept within prepared area. Conditioner being applied.,
- * One of the many local repairs completed.,

Application Situation

Rubber lined water boxes of condensers.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet HEX-4. Spark testing identified defects which were then locally repaired.

Belzona Facts

Excellent adhesion and ambient curing properties of Belzona Elastomer allow effective long term repairs to be carried out within the confines of the water box.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA