# **BELZONA REPAIRS TURBINE WICKET GATES**

ID: 5599

Industry: Power Customer Location: Hydropower Plant, USA

Application: CEP-Centrifugal Pumps Application Date: 1998

Substrate: Steel

Products: \* Belzona 1221 (Super E-Metal),

\* Belzona 1341 (Supermetalglide),

#### **Problem**

The wicket gates were suffering from cavitation damage due to the water flow. This unit has 1,000,000 gallons of water per minute running through it.







## **Photograph Descriptions**

- \* Cavitation damage to the wicket gate,
- \* Close up of the repaired area with no more cavitation,
- \* Completed application,

## **Application Situation**

Wicket gates

## **Application Method**

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-5.

### **Belzona Facts**

The hydropower plant saved time and money by repairing the wicket gates in situ instead of removing them from the plant to be repaired.

www.belzona.com