

EASY LINTEL REPAIR WITH BELZONA

ID: 6435

Industry: *Buildings & Structures*

Application: *WPA-Wall Problem Areas*

Substrate: *Concrete and Steel*

Products: ** Belzona® 4141 Belzona® 4911 ,*

Customer Location: *Housing Association, Cleveland, UK*

Application Date: *2017*

Problem

The entire front face of the concrete "Boot" lintel had failed due to re-bar corrosion. The customer wanted a long-term solution without having the need to disturb the structure.



Photograph Descriptions

- * 1. Overview (after repair) ,
- * 2 & 3. Damaged Lintel ,
- * 4. Completed repair ,

Application Situation

Residential Property

Application Method

Application carried out in accordance with Belzona system leaflet WPA-4

Belzona Facts

The application was completed in just 2 hours. Conventional replacement would have been costly, time consuming and disruptive. The customer has used Belzona 4141 before and is very happy with the results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve