

# BELZONA RECLAIMS DAMAGED BOWLING ALLEY SIDEPLATE

ID: 645

Industry: *Buildings & Structures*

Customer Location: *Bowling Centre, Calgary, Alberta, Canada*

Application: *WPA-Wall Problem Areas*

Application Date: *November 2005*

Substrate: *Hardwood maple slabs*

Products: *\* Belzona® 8111 (Mouldable Wood),*

## Problem

*This damage if not repaired would damage customer bowling balls and lead to loss of sanctioning and income.*



## Photograph Descriptions

- \* Damaged hardwood slab, 3/4-inch deep ,
- \* First layer of Belzona® 8111 applied ,
- \* Final layer of Belzona® 8111 after sanding ,
- \* Kick plate reinstalled over damaged area ,

## Application Situation

Damaged side plate on the pin deck

## Application Method

The method used was similar to rebuilding pitting corrosion on vertical vessel walls, a modified Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

The customer had tried other non-traditional methods such as body filler and drywall mud all unsuccessful.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Q 09335

ISO 14001:2015

EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve