# Leaking Parapets on Grade 1 Listed Church coated with Belzona 3131

ID: 8354

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas

Substrate: Lead

Products: \* Belzona 3921 (GSC-Conditioner),

\* Belzona 3131 (WG Membrane),

\* Belzona 9361 Reinforcing Sheet,

#### **Problem**

Water was leaking through the damaged/cracked parts of the lead parapet.







Customer Location: Birmingham, UK

Application Date: 3rd August 2020

### **Photograph Descriptions**

- \* 1) Cleaning the substrate with Doff Cleaning machine. ,
- \* 2) Lead parapet prior to application,
- \* 3) Completed Application,

## **Application Situation**

This grade 1 listed church was suffering with severe water leaks which if carried on would have caused internal damage. Numerous repairs were completed on the existing lead substrate, however it never cured the problem.

#### **Application Method**

The parapet of the roof was cleaned using a Doff machine at 160 degrees. Belzona 3921 conditioner was applied to the substrate and left over night. A first coat of Belzona 3131 was applied whilst laying Belzona 9361 reinforcing sheet over the top. A second coat of Belzona 3131 applied over the top to complete the application. This was completed in accordance with Belzona System Leaflet RPA-06.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair : Protect : Improve

Belzona Facts Belzona cost approximately ten times less than using a traditional method such as felt.