# Damaged Conveyor Belt Rescued By Belzona.

ID: 8473

Industry: Mining & Quarrying Customer Location: Quarry in the Midwestern US

Application: SHM-Solids Handling Machinery Application Date: 1990

Substrate: Rubber

Products: \* Belzona 2111,

\* Belzona 2911 Conditioner,

\* Belzona 9111 Cleaner/Degreaser,

#### **Problem**

A sharp object had caught in the screen section and gouged the almost-new belt down to the reinforcing cord. Having the interior of the belt constantly exposed to the outdoor wet environment would shorten its life. The only other alternative was a costly replacement.









### **Photograph Descriptions**

- \* 1. Undercutting and roughening the repair area,
- \* 2. Conditioning with Belzona 2911,
- \* 3. Applying Belzona 2111 to fill the gouge. ,
- \* 4. A piece, cut from the retired belt showing Belzona 2111 fully intact,

## **Application Situation**

Scored conveyor belt on a screen separator

### **Application Method**

The belt was cleaned of dirt and sand. The gouged are was undercut using a utility knife and roughened using a hand roughing brush. Then it was cleaned, using a rag LIGHTLY moistened with Belzona 9111. Belzona 2911 was applied using a cut-back brush. Belzona 2111 was mixed and applied to fill the gouge.

# **Belzona Facts**

The Belzona repair was a fraction of the cost of a new belt. On a visit to this customer some 6-7 years later he said he had recently replaced the belt as it was severely worn by the countless tons of material passed over it. When asked about the Belzona repair he

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

said it had held up well and pointed to a rolled up belt in some weeds. He allowed the removal of a piece of the old belt where it had been repaired with Belzona 2111. (see photo 4) It is now a prized sales aid. The longevity of the repair can be attributed to the excellence of Belzona 2111 and the diligence applied in prep. As you can see in the photos, the repair was begun in the afternoon and completed after the sun had set.