

Repair of PVC pipe with leak from failed fiber glass installation

ID: 9493

Industry: Steel & Metal Processing

Customer Location: Hamilton, Ontario

Application: VPF-Valves, Pipes and Fittings

Application Date: July 2024

Substrate: PVC

Products: Belzona 1212, Belzona 1982 (SuperWrap II), Belzona SuperWrap, Belzona 9111 (Cleaner Degreaser)

Problem

Major leaks was experienced from a failed fiber glass installed earlier by customer to fix problem.



Failed fiber glass



Newly installed Belzona Superwrap II



Belzona Super wrap installed successfully.

Application Situation

Customer was relying not only on the performance of Belzona Super wrap II but also on the quick turn around of our range of solutions.

Application Method

The failed fiber glass was abraded with the aid of a power tool after which the surface was wiped clean using the cleaner/ degreaser Belzona 9111. After drying, Belzona 1212 was mixed and apply with Belzona Super wrap installed afterwards.

Belzona Facts

Belzona was not only able to seal the leak in a couple of minutes but also completed the whole installation and the equipment put back in service as stipulated in the product IFU. Follow up with customer confirmed that there was no leak or sipping as the Super wrap II successfully solve the issue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve