Know-How *in Action*

élite series

Vol.XXXI No.162

BELZONA REFURBISHED LOADING DOCK STILL GOOD 7 YEARS ON

CUSTOMER
Business complex, Brisbane, Queensland, Australia

APPLICATION DATE
May 2009

APPLICATION SITUATION
Loading dock and car park of a multi use business complex.

PROBLEM
The Loading dock and car park were old and in need of a facelift as all of the original coating had been worn away.

PRODUCTS
Belzona 5231 (SG Laminate)
Belzona 4411 (Granogrip)

SUBSTRATE
Concrete

APPLICATION METHOD
The application was carried out in accordance with Belzona System Leaflets FPA-4 and FPA-8. The floor area was prepared using a dustless diamond grinder then coated with 2 coats of Belzona 5231. The line markings, chevrons and wording were then reinstated using Belzona 4411 in a single coat of safety yellow.

BELZONA FACTS
Belzona materials were chosen due to their ease of application, proven longevity and incorporated grip system that provides a safer and more durable finish than conventional floor paints. This decision has proven to be the right one as the floor is still in a serviceable condition 7 years later

PICTURES
1. The original condition of the floor area
2. Surface preparation in progress
3. The finished application showing the coated floor and reinstated lines, wording and chevrons
4. The floor after 7 years in service

1.

2.

3.



4.

Copyright © Belzona International Limited 2013