Know-How*in Action*

Vol.XXXIV No.63

BELZONA RESURFACES LAB TABLES

CUSTOMER
Atlanta, GA, USA

APPLICATION DATE
February 2008

APPLICATION SITUATION
Surface of the lab table

PROBLEM
At Georgia Tech, customer wanted to provide a durable surface without having to replace soapstone tables of 40 years of wear and tear have degraded tables.

PRODUCTS
Belzona 5811 (Immersion Grade)

SUBSTRATE
Soapstone

APPLICATION METHOD
Sanding tables to provide a good profile. Then applied two coats of Belzona 5811.

BELZONA FACTS
The university was able to refurbish the tables and labs at a fraction of the cost to replace. The table tops were refurbished in two days as compared to two weeks for replacement.

PICTURES
1. View of original table
2. Application of first coat
3. Completed application
4. After 5 years, another lab top table was being repaired. Lab was being rebuilt, but the tops were remained

1.

2.

3.

4. 

For more examples of *Belzona Know-How In Action*, please visit **http://khia.belzona.com**

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2018