

NO JOB IS TOO SMALL FOR BELZONA

CUSTOMER

Motocross enthusiast - Northern Italy (Piacenza)

APPLICATION DATE

January 2005

APPLICATION SITUATION

Yamaha YZ 250 cc - 2001

PROBLEM

Activities during a motocross race caused a stripped thread. Piece of equipment quite expensive.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Aluminium casting

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-2. The area was post-cured at 50° C for five hours to ensure that the oil seals were not damaged.

BELZONA FACTS

Still in service after months of intensive use.

PICTURES

1. Yamaha YZ 250
2. Broken thread
3. Completed work
4. See the rebuilt fillet



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

