

## BELZONA PROTECTS OIL/GAS SEPARATORS

### CUSTOMER

International Equipment Manufacturer to the Oil Industry

### APPLICATION DATE

1994

### APPLICATION SITUATION

Two standard designs of test separators used around the world and particularly in the Middle and Far East.

### PROBLEM

Severe deterioration to the internal surfaces of the vessels due to erosion-corrosion and SRB attack.

### PRODUCTS

Belzona® 1391

### SUBSTRATE

Steel

### APPLICATION METHOD

The application was carried out in accordance with the Belzona Know-How System Leaflet TCC-3

### BELZONA FACTS

Belzona® 1391 is now specified by this company for refurbishment of oil/gas separators and also for new separators. The alternative is replacements at \$200,000. Belzona refurbishment saves about \$150,000 per separator. Total worldwide refurbishment programme is going to be worth approximately \$2 million.

### PICTURES


1. General view of separator
2. Application of Belzona® 1391 underway in a confined internal space
3. Completed application to all internal surfaces of the separator



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve