

BELZONA REPAIRS SUN DAMAGE ON ROOF

CUSTOMER

Railway Engineering Workshops in Northern England

APPLICATION DATE

June 1996

APPLICATION SITUATION

Extraction Ducting

PROBLEM

Leaks at seams, bituminous coating is damaged

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Concrete treated with bitumen

APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

The tar was severely damaged due to the effects of the sun; further application of the bituminous coating would have also failed. Belzona® 3111 solved the problem on the roof.

PICTURES

1. Failed bituminous coating
2. Seam areas addressed
3. Ducting completely protected and sealed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

