

BELZONA REFURBISHES THE FLOORS

CUSTOMER

Airport Food Service in Missouri

APPLICATION DATE

February 1996

APPLICATION SITUATION

Wash area floor for aircraft food service carts

PROBLEM

Water was trapped under the tile, causing the tile to break up and providing a haven for bacteria and mold. Pushing the carts over rough, broken, and missing tile posed a serious safety hazard as well.

PRODUCTS

Belzona® 4131 (Magma Screed)

SUBSTRATE

Concrete

APPLICATION METHOD

Old concrete was removed and 1 1/2" voids were left in several areas. Belzona® 4131 (Magma Screed) was applied over the areas where the minimum depth was 3/8". The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The application covered a 72 square foot area and took only two hours to complete. The wash area is now a safer and cleaner place to work.

PICTURES

1. Removing old tile, dirt and concrete
2. Beginning application of Belzona® 4131
3. Job almost completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve