

BELZONA KEEPS THE BEER BREWING

CUSTOMER

Brewery in Texas

APPLICATION DATE

March 1995

APPLICATION SITUATION

Bromine chemical containment area at brewery

PROBLEM

A chemical containment area was leaking chemicals around the perimeter of the area.

PRODUCTS

Belzona® 4311 (Magma CR-1)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Costly environmental regulatory fines were averted by using Belzona. The chemicals were contained and the dike was protected.

PICTURES

1. Work begins early in the day.
2. Following application of the Belzona® 4911 (Magma TX Conditioner) primer coat, the first coat of Belzona® 4311, red, was applied. Application of the second gray coat is in progress.
3. The finished Belzona® 4311 protective coating is now ready for service.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve