

BELZONA TANK FARM

CUSTOMER

Chemical Plant in South Alabama, USA

APPLICATION DATE

August, 1995

APPLICATION SITUATION

Chemical containment area (5000 sq. ft.)

PROBLEM

Harsh chemicals attacking existing substrate which was installed in 1993.

PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 4311 (Magma CR-1)

SUBSTRATE

Concrete and Polymeric Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets TCC-9 and TCC-15.

BELZONA FACTS

The previous polymeric concrete repair material was damaged by chemical attack. The concrete was repaired and all areas protected.

PICTURES

1. View of damage to polymeric repair compound.
2. Application of Belzona® 4311 in progress.
3. 5000 sq. ft. area protected.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve