

BELZONA EMERGENCY IN A COOLING TOWER

CUSTOMER

Power Plant in Northwest Florida, USA

APPLICATION DATE

December, 1996

APPLICATION SITUATION

Cooling tower containment

PROBLEM

Crack (leak) in the containment wall and floor.

PRODUCTS

Belzona® 3121 (MR-7)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-1.

BELZONA FACTS

The repair was performed overnight and the plant was operational early the next morning. It is estimated that the plant saved \$6,000 in water cost alone.

PICTURES

1. The leak; sand bags used to hold back as much water as possible.
2. The completed repair.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

