

BELZONA ROOF REPAIR, EIGHT YEARS AND HOLDING

CUSTOMER

Power Plant in Georgia

APPLICATION DATE

1989

APPLICATION SITUATION

Expansion joints of slab roof above generators

PROBLEM

Severe water leakage

PRODUCTS

Belzona® 3111 (Flexible Membrane)

Belzona® 3911 (PSC Surface Conditioner)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

Eight years ago approximately \$30,000 in Belzona product was used and solved the leakage problem. Based on the success, the plant recently purchased \$50,000 of material to fix the other side of the roof, basically to seal the joints and cracks in the concrete slab.

PICTURES

1. Joints were leaking.
2. Belzona® 3111 applied 8 years ago and still preventing leakage.
3. Another view of the roof.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve