

## BELZONA FLOATING ORANGE HOSE

### CUSTOMER

Offshore Oil Port in the Gulf of Mexico, USA

### APPLICATION DATE

Ongoing since 1994

### APPLICATION SITUATION

Floating rail hose

### PROBLEM

Massive, deep cut in the hose.

### PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

Belzona® 9341 (Reinforcement Tape)

### SUBSTRATE

Rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

### BELZONA FACTS

Replacement of the 45 foot long hose would have cost approximately \$40,000 with long delivery time. The Belzona application cost only \$1,000 saving the customer nearly \$40,000.

### PICTURES

1. Repair procedure in progress using Belzona® 9341 and special layering technique.
2. Belzona® 2211 almost cured.
3. Floating hose ready to go.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve