

BELZONA SLIDES THE CHIPS OFF THE BARK SHAKER

CUSTOMER

Pulp Mill in Alabama, U.S.A.

APPLICATION DATE

1992

APPLICATION SITUATION

Bark shaker sorts and distributes bark to the boiler.

PROBLEM

Bark builds up and clogs the shaker.

PRODUCTS

Belzona® 1341 (Supermetalgilde)

SUBSTRATE

Carbon steel

APPLICATION METHOD



The application was carried out in accordance with Belzona Know-How System Leaflet SHM-13.

BELZONA FACTS

The application is touched-up every two years and prevents the bark from sticking to the steel. Recently a new bark shaker has been coated. The customer is extremely happy with the application.

PICTURES

1. The bark shaker.
2. Belzona® 1341 provides a slick surface and the bark slides off.
3. Another view of the 30 foot long, 8 foot wide bark shaker coated with two coats of Belzona® 1341.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve