

BELZONA MANWAY OPENING

CUSTOMER

Petroleum refinery in Texas.

APPLICATION DATE

1991

APPLICATION SITUATION

Manway opening on chemical storage tank.

PROBLEM

Opening on chemical tank was corroded to the point where a good seal was not possible.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Stainless Steel

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-10.

BELZONA FACTS

For only \$128 in Belzona® 1111, downtime and expensive welding was averted. The repair has held for many years, and is still in perfect condition.

PICTURES

1. Surface preparation performed with the repair area taped off.
2. Manway rebuilt.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve