

## BELZONA PROVIDES LONG LASTING PIPE SUPPORTS

### CUSTOMER

International Oil Company

### APPLICATION DATE

February, 1997

### APPLICATION SITUATION

Product and services pipelines at oil terminal. There are 5 separate pipelines of differing diameter.

### PROBLEM

Severe corrosion of original pipe supports and pipe in way of support points.

### PRODUCTS

Belzona® 1121 (Super XL-Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

New pipe saddle supports and wear pads were bonded in place in accordance with Belzona® Know-How System Leaflet VPF-15.

### BELZONA FACTS

Welding of new supports was not possible due to unloading of LPG and oil from tankers at regular intervals. Tests showed Belzona® 1121 provided corrosion resistant bond that required 25 tons to remove bracket.

### PICTURES

1. General view of terminal
2. Typical corroded state of original supports
3. New saddle bonded in place prior to re-painting of the pipe



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

