

## BELZONA KEEPS BEET SLICER RUNNING

### CUSTOMER

Sugar Beet Mill in North Dakota, U.S.A.

### APPLICATION DATE

1983

### APPLICATION SITUATION

Beet slicer shaft

### PROBLEM

Bearing failure damaged beet slicer shaft

### PRODUCTS

Belzona® 1111 (Super Metal)

### SUBSTRATE

Carbon Steel

### APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

### BELZONA FACTS

Repair allowed customer to save time and money by avoiding disassembly of machinery.

### PICTURES

1. View of damaged shaft
2. Application of Belzona® 1111.
3. Use of a former to rebuild shaft.
4. Completely rebuilt shaft.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve