

BELZONA SOLVES DREDGE PUMP WOES

CUSTOMER

Marine contractor, Panama City, Florida, U.S.A.

APPLICATION DATE

August 1999

APPLICATION SITUATION

Dredge pump repair.

PROBLEM

Large roots and stones damaged cutwater and stripped rubber coating from pump.

PRODUCTS

Belzona® 2311 (SR-Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-1.

BELZONA FACTS

Application proceeded rapidly using Belzona® 2311 (SR-Elastomer) to achieve full mechanical properties in less than two hours with minimal downtime for the dredge pump operator.

PICTURES

1. The damage.
2. Completed repair.
3. Dredge pump ready for service.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

