

BELZONA REPAIR TO TURBO-PULPER

CUSTOMER

UK Paper Mill

APPLICATION DATE

1998

APPLICATION SITUATION

Stainless steel sealing ring inside Turbo-pulper.

PROBLEM

Erosion from pulp had worn away the sealing ring exposing the Stainless steel bolts.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Stainless steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

To remove sealing ring and replace would have taken a long time and interfered with production. Belzona® application carried out within normal shutdown period and has prevented further erosion of the sealing ring and bolts.

PICTURES

1. The degree of erosion on the sealing ring and bolts clearly evident.
2. Application underway inside the pulper.
3. Sealing ring and bolts completely encapsulated with Belzona® 1111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve