

BELZONA HEATING PIPE FITTINGS ABOARD SUPERTANKER

CUSTOMER

A 600 foot supertanker barge at Tampa Bay, Florida, U.S.A.

APPLICATION DATE

January 1997

APPLICATION SITUATION

Ship was being refitted and repaired so a new type of fuel additive could be carried. Heater lines keep the cargo warm and fluid.

PROBLEM

Pipe fittings continued to leak.

PRODUCTS

Belzona® 1211 (E-Metal)

Belzona® 1111 (Super Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

Millions of dollars in lost revenue were at stake. Other options such as silver solder and expensive fittings from Europe. Belzona solved the emergency quickly and cost effectively, allowing the ship to sail on time.

PICTURES


1. Following surface preparation, a collar was used.
2. Application of product.
3. Pipe fittings and sea dogs are happy with the repair.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

