

BELZONA LEAK SEALING ON VALVES

CUSTOMER

Ministry of Water, Jordan

APPLICATION DATE

1998

APPLICATION SITUATION

Emergency water valves, 1.6m and 2.2m diameter, in dam

PROBLEM

Erosion-corrosion leading to water leakage

PRODUCTS

Belzona® 1311

Belzona® 1321 (Ceramic S-Metal)

SUBSTRATE

Cast iron and steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflets VPF-1 and VPF-2

BELZONA FACTS

The larger valve was repaired following successful refurbishment of the smaller one

PICTURES

1. The degree of water leakage clearly evident from the 1.6m valve
2. Work underway on the 2.2m valve
3. Application completed
4. The two valves re-installed at the dam base



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve