

## BELZONA RESTORES JAPANESE ALUMINUM END COVERS

### CUSTOMER

Paperboard Mill in Ontario, Canada

### APPLICATION DATE

September 1999

### APPLICATION SITUATION

Aluminum end covers from formers of Kobayashi paper machine. Six formers with two end covers per machine.

### PROBLEM

Severe erosion caused by a combination of corrosive environment and abrasion of a fanbelt.

### PRODUCTS

Belzona® 1121 (Super XL Metal)

Belzona® 1321 (Ceramic S-Metal)

### SUBSTRATE

Aluminum

### APPLICATION METHOD


The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-10.

### BELZONA FACTS

Savings to the customer for six (6) pairs of formers exceeded \$60,000. The parts would come from Japan which saved them 8 to 12 weeks worth of downtime. The repaired parts should outlast new ones.

### PICTURES

1. The corroded end cover.
2. Work in progress.
3. The end cover repaired and ready for service.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

