

DUCT SEALING WITH BELZONA® 4211

CUSTOMER

Telecommunications in India

APPLICATION DATE

August 1999

APPLICATION SITUATION

Underground chambers containing cable joints

PROBLEM

Water leakage into the chambers causing cable joints to be submerged and extensive disruptions to telephone lines. Problem is particularly great during the monsoon.

PRODUCTS

Belzona® 4211 (Magma-Stop)

SUBSTRATE

Concrete, rubber and PVC

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11b suitably modified

BELZONA FACTS

Live" leaks were effectively sealed eliminating major disruption to the local and national communication systems."

PICTURES

1. Access to the chambers
2. The cable connections
3. & 4. Application of Belzona® 4211 underway



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve