

BELZONA REPAIR AND PROTECTION OF STABILISER SHAFT

CUSTOMER

Shipping Company, Monaco

APPLICATION DATE

1995

APPLICATION SITUATION

Stabiliser shaft

PROBLEM

Severe pitting corrosion in-board of bearing

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-1.

BELZONA FACTS

Belzona® was used because the repair could be done without dismantling

PICTURES

1. General view of the stabiliser shaft
2. After grit blasting, degree of erosion-corrosion damage clearly evident
3. Application of Belzona® 1111 being completed



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

