

BELZONA® 4131 REPAIRS TO SPALLED CONCRETE

CUSTOMER

Local Authority

APPLICATION DATE

1999

APPLICATION SITUATION

Canopy over a busy shopping area

PROBLEM

Extensive spalling had made using the hand-rail unsafe.

PRODUCTS

Belzona® 4131 (Magma-Screed)

SUBSTRATE

Concrete and stainless steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

BELZONA FACTS

When work initially started damage was found to be more extensive than originally thought. Old railings were replaced. Rapid repairs with Belzona® 4131 ensured minimum disruption.

PICTURES

1. General view of the site with specially boarded up Acrows insisted on by safety officials.
2. The degree of concrete damage clearly evident.
3. Rebuilding complete and gutter re-instated.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve