

BELZONA® 3111 PROVEN PERFORMANCE

CUSTOMER

Chemical plant in the United Kingdom

APPLICATION DATE

1986 and 1988

APPLICATION SITUATION

Roof areas over offices and workshops.

PROBLEM

Severe water penetration, particularly through joints, seams, glazing units and gutters.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Asbestos and asphalt

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, -3 and -6.

BELZONA FACTS

Belzona was chosen over other materials as previous repairs with competitive materials on the site had underperformed. Belzona system lived up to expectations and was in excellent condition when inspected in 1997.

PICTURES

1. Work underway on the workshop roof.
2. Horizontal area of office roof undergoing treatment.
3. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

