

BELZONA KEEPS WORN HOSE WORKING

CUSTOMER

Shipping company in Canada

APPLICATION DATE

November 2000

APPLICATION SITUATION

Worn rubber hose

PROBLEM

The unloading cement hose had worn through to the reinforcement wire.

PRODUCTS

Belzona® 2311 (SR-Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

A quick reliable repair was required and other than replacement, Belzona was the only option.

PICTURES

1. Overview of damaged area.
2. Loose pieces have been removed.
3. The conditioner, reinforcement sheet and Belzona® 2311 have been used to fill area.
4. The finished repair.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve