

BELZONA SPECIFIED PROTECTION OF SOAP PLODDERS

CUSTOMER

International soap manufacturer - Malaysia

APPLICATION DATE

1999

APPLICATION SITUATION

Silumin worms from soap plodders used in the manufacture of soap.

PROBLEM

Wear and chemical attack of the worm's surface.

PRODUCTS

Belzona® 1391

SUBSTRATE

Aluminium alloy

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-14.

BELZONA FACTS

This customer had tried many alternatives to protect these worms, which are used worldwide. With the success of Belzona, they have standardized the use of Belzona® 1391 as the only material capable of operating in the harsh conditions.

PICTURES

1. General view of plodder worm after cleaning.
2. Application underway.
3. Completed application.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve