

## BELZONA HELPS KEEP THIS POWER PLANT ON-LINE

### CUSTOMER

Power plant in eastern Kansas, U.S.A.

### APPLICATION DATE

Winter 2000

### APPLICATION SITUATION

Damaged armature shaft.

### PROBLEM

A bearing seizure damaged the armature shaft in fuel generator.

### PRODUCTS

BELZONA® 1111 (Super Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

### BELZONA FACTS

Belzonas famous in place split former repair used less than \$50 worth of material and saved this company thousands of dollars in repair costs and downtime.

### PICTURES

1. Surface preparation.
2. The former is being tightened
3. The former is removed.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve